



RECALL OF GASGAS MC-E 5 MODELS OF MODEL YEAR 2021: CHECK OF BATTERY VENT VALVE

Valid for all markets

GASGAS recalls GASGAS MC-E 5 models of model year 2021 to the workshops of authorized GASGAS dealers in order to check the battery vent valve due to deviations in the production process.

In the production process of the battery vent valve, nonconformities may have occurred. The vent valve may be missing on some vehicles, which may lead to unsafe battery conditions, e.g. after water intrusion. For this reason, a check if the vent valve is installed has to be performed on all affected vehicles.

Customers to whom the affected motorcycles have already been delivered are being personally informed by letter and are asked to immediately contact an authorized GASGAS dealer to arrange an appointment. In addition, customers can check online in the "Service" area on the GASGAS website if their motorcycle is affected by the recall.


The check of the bleeder valve takes approximately 10 minutes and the retrofit of the bleeder valve, if necessary, takes around 25 minutes. The check and retrofit can be carried out by authorized GASGAS dealers only. This check and possible retrofit of the bleeder valve is a free-of-charge service for customers performed under warranty.

GASGAS

GASGAS Motorcycles GmbH

Stallhofner Straße 3
5230 Mattighofen
Austria

+43 7742 6000
info@gasgas.com



Bank Oberbank Mattighofen
IBAN AT53 1910 0000 3834 4000
BIC DEUTATWW

VAT NUMBER ATU74882638
FN 521678 z
Ried im Innkreis