



## LOCKING SLIP PINS RECALL ON 2021 & 2022 GASGAS ENDURO BIKES

### ALL EC MODELS TO BE INSPECTED AT AUTHORISED GASGAS DEALERSHIP

Valid for all markets

GASGAS is recalling all of its 2021 & 2022 EC enduro bikes due to the availability of improved locking split pins for the brake pad holding brackets in the front and rear brake calipers. Owners of our enduro models are required to contact their local GASGAS dealer immediately to arrange a fast and simple check over of their machine by one of our trained technicians.

It's highly likely that not all of our enduro models are affected by this potential problem. But for peace of mind and continued riding enjoyment, please visit your local GASGAS dealership where they will assess your bike and rectify the problem if required.

Customers who have already acquired one of the above-mentioned motorcycles are being informed by a personal letter and are asked to immediately contact an authorized GASGAS Dealer to arrange an inspection appointment.

In addition, customers can check online in the 'Service' area of the GASGAS website to determine if their motorcycle is affected by this recall. The check and replacement of all parts involved will be carried out at no cost to the customer and must be performed by authorized GASGAS Dealers only.

Further information on all authorized dealers can be found on the GASGAS website:


<https://www.gasgas.com/en-int/dealer-search.html>

# GASGAS

#### GASGAS Motorcycles GmbH

Stallhofner Straße 3  
5230 Mattighofen  
Austria

+43 7742 6000  
info@gasgas.com



Bank Oberbank Mattighofen  
IBAN AT53 1910 0000 3834 4000  
BIC DEUTATWW

VAT NUMBER ATU74882638  
FN 521678 z  
Ried im Innkreis