

FRONT BRAKE RECALL ON 2022 GASGAS ENDURO BIKES

ALL EC MODELS TO HAVE FRONT BRAKE INSPECTION AT AUTHORISED GASGAS DEALERSHIP

Valid for all markets

GASGAS is recalling all of its 2022 EC enduro bikes as there may be a small issue with the front brake caliper. Owners of our enduro models are required to contact their local GASGAS dealer immediately to arrange a fast and simple check over of their machine by one of our trained technicians.

It's highly likely that not all of our enduro models are affected by this potential problem. But for peace of mind and continued riding enjoyment, please visit your local GASGAS dealership where they will assess your bike and rectify the problem if required.

Customers who have already acquired one of the above-mentioned motorcycles are being informed by a personal letter and are asked to immediately contact an authorized GASGAS Dealer to arrange an inspection appointment.

In addition, customers can check online in the 'Service' area of the GASGAS website to determine if their motorcycle is affected by this recall. The check and replacement of all parts involved will be carried out at no cost to the customer and must be performed by authorized GASGAS Dealers only.

Further information on all authorized dealers can be found on the GASGAS website:

https://www.gasgas.com/en-int/dealer-search.html



